

DIGI-LINK Smart Security COMPATIBILITY (1480/540)

★Recommended Installation Option: NS-4 or NT-4 connectors make CAN-H/L connections fast, easy & secure.

★Useful Enhancement: TR537S Two-way Paging Remote offers detailed notifications and control.

TOYOTA

IMPORTANT ○=Compatible △=No Door Lock Control

Current as of: Jan.18,2019

Car Make	Car Model	Car Year	Car has SMART Key?	Compatible with SMART Key, Factory Keyless?	OPTIONAL TR537S Paging System	CAN Connection	IMPORTANT NOTES			Notes about vehicle we tested	1480 Vehicle Firmware
							Regarding DOOR LOCKING via optional TR537S Paging System: - When Armed by Factory Remote Lock and then Disarmed by the Pager, doors will NOT Unlock. - △ symbol in the "OPTIONAL TR537S..." column means only Arm & Disarm & Notifications are available.	Automatic Speed-Lock Feature	Unlocks on Parking Brake		
86	DBA-ZN6	2012.04 ~	NO Notes1&2	○ Note1, Note2	○	OBD	No Hazard Flash while Ignition is ON, even with programmable features 3 or 4 or 7 enabled.	Note1 : Must Disarm before opening Trunk via keyless remote.	Unlocks on Parking Brake	MT	86_N6_NO_SMRT_V2_3
			YES	○	○			It is possible to open the Trunk via the 2-way pager remote.	Note 2 : Not Compatible	AT Note2	86_N6_SMRT_MT_V2_0
IQ	#GJ10	2008.11 ~ 2016.03	Yes/No	○	○	OBD	MT (manual transmission) cars disable Automatic Speed-Lock.				IQ_I10_V2_1
C-HR	ZYX10, NGX50	2016.12 ~	YES	○	△	2wire ▼	※No Hazard Flash while Ignition is ON, even with programmable features 3 or 4 or 7 enabled. ※No Auto Speed-Lock function. ※Optional NS-4 connectors required for CAN wire connections. ※When installing Starter Kill, use optional KDR-2B Starter Kill Relay.				CH_R_V2_1
RAV4	ACA3#W	2005.11 ~ 2016.07	Yes/No	○	○	OBD					RAV4_A30_V2_1
SAI	AZK10	2009.12 ~ 2017.12	YES	○	○	OBD					SAI_AZK_10_V2_1
Aqua	NHP10	2011.12 ~ 2015.10	NO	○Note1	○	OBD	※Hazard Flash Feature: Not possible while Ignition = ON. (IG Protected Mode triggers, Remote Start Operation, Door Trigger while IG=ON) Note1: Automatic Speed-Lock Function not available on cars without SMART key.			Note1	VITZ_P130_NO_SMRT_V2_0
			YES	○	○					SMART key equipped	AQUA_P11W_SMRT_V2_1
	NHP10 TSS & SMART key	2015.11 ~	YES	○	○	2wire▼	※TSS equipped vehicles require optional NS-4 Post-Tan connectors for CAN wire connections			TSS equipped	P11_TSS_W_SMRT_V2_1
Avensis	ZRT272W	2011.06 ~ 2018.04	YES	○	○	OBD	Car maker made minor changes to car after Oct.2015 and we have not checked those models.				AVENSIS_ZRT272W_V2_3
Allion	NZT260, ZRT26#	2007.06 ~ 2014.09	Yes/No	○	○	OBD	Automatic Speed-Lock Functionality has not been confirmed.				ALLION_T260_V2_1
	NZT260	2014.10 ~ 2016.05	YES	○*	○		*No Trunk-open detection and no Auto Speed-Lock Function.			1500cc i-stop	AURIS_E18#_V2_0
	NZT260 TSS equipped	2016.06 ~	YES	○*	○		2wire▼	※Same firmware as Auris 180. ※TSS equipped vehicles require optional NS-4 Post-Tan connectors for CAN wire connections			TSS equipped
Alphard Alphard Hybrid	GGH2#W, ANH2#W ATH20W	2008.05 ~ 2015.01	Yes/No	○	○Note1	OBD	※Compatible with Power Back Door equipped cars ※UPS-33 recommended for non-HV cars Note1: When Locking with factory keyless or SMART, if you later Unlock with the optional Pager remote, the factory alarm won't Disarm. You must use the factory remote to Unlock and Disarm factory alarm.				ALPHARD_H20W_V2_1
	GGH3#W, AGH3#W AYH30W	2015.01 ~ 2017.12	YES	○ Also Arms on Reservation Lock	○Note1	OBD	Note1: Factory Alarm & Mirror Closer not controlled by optional Pager.	Hazard Flash Feature: Not possible while Ignition = ON	※UPS-33 recommended for non-HV cars. ※When installing Starter Kill, use optional KDR-2B Starter Kill Relay.		ALPHARD_H30W_V2_0
	GGH3#W, AGH3#W AYH30W TSS equipped	2018.01 ~	YES		△	2wire ▼	※Hood-open detection OK ※Open Back Door only after Unlocking. ※NT-4 Post-Tan Connectors required. ※1480/540 OS Firmware T39 required.	(IG Protected Mode triggers, Remote Start Operation, Door Trigger while IG=ON)		Feb. 2018 GGH30W	TOYOTA_RAB2_V6_0
IST (xA)	NCP11#, ZSP110	2007.07 ~ 2016.04	Yes/No	○	○	OBD					IST_P110_V2_1
WISH	ZGE2#W	2009.04 ~ 2017.10	Yes/No	○	○Note1	OBD	Note1: We have not confirmed proper 1480/540 operation on cars with the factory alarm option installed.				WISH_ZGE2#_V2_3
Vanguard	ACA33W, GSA33W	2007.08 ~ 2013.11	Yes/No	○	○	OBD					VANGUARD_A33_V2_1
Vitz	KSP90, SCP90, NCP9#	2005.02 ~ 2010.12	Yes/No	○	○△Note1	OBD	△: MT cars don't support Auto Speed-Lock No Door Lock Control by optional Paging System. Note1: Cars without SMART have no Door Lock Control when using optional Paging System				VITZ_P90_V2_4
	KSP130, NSP13# NCP131	2010.12 ~	No	○	○	OBD	※Hazard Flash Feature: Not possible while Ignition = ON. (IG Protected Mode triggers, etc.) ※MT cars don't support Auto Speed-Lock.				VITZ_P130_NO_SMRT_V2_0
			Yes	○	○		※June 30, 2015 & later models: Cars with TSS must connect CAN wires separately (can't use OBD)		SMART key equipped	VITZ_P131_W_SMRT_V2_0	
	KSP130, NSP13# NCP131 TSS equipped	2015.07 ~	No	○	○	2wire ▼	※Hazard Flash Feature: Not possible while Ignition = ON. (IG Protected Mode triggers, etc.) ※No Auto Speed-Lock function. ※Optional NS-4 connectors required for CAN wire connections				
Yes			○	○	※TSS (Toyota Safety Sense) equipped vehicle.			SMART key equipped	VITZ_P131_W_SMRT_V2_0		
Vitz Hybrid	NHP130 TSS equipped	2017.01 ~	Yes	○	○					SMART key equipped	

DIGI-LINK Smart Security COMPATIBILITY (1480/540)

★Recommended Installation Option: NS-4 or NT-4 connectors make CAN-H/L connections fast, easy & secure.

★Useful Enhancement: TR537S Two-way Paging Remote offers detailed notifications and control.

TOYOTA

IMPORTANT ○=Compatible △=No Door Lock Control

Current as of: Jan.18,2019

Car Make	Car Model	Car Year	Car has SMART Key?	Compatible with SMART Key, Factory Keyless?	OPTIONAL TR537S Paging System	CAN Connection	IMPORTANT NOTES		Notes about vehicle we tested	1480 Vehicle Firmware
							Regarding DOOR LOCKING via optional TR537S Paging System: - When Armed by Factory Remote Lock and then Disarmed by the Pager, doors will NOT Unlock. - △ symbol in the "OPTIONAL TR537S." column means only Arm & Disarm & Notifications are available.			
Vellfire Vellfire Hybrid	GGH2#W, ANH2#W ATH20W	2008.05 ~ 2015.01 2011.11	Yes/No	○	○Note1	OBD	※Compatible with Power BackDoor equipped cars. ※UPS-33 recommended for non-HV cars. Note1: When Locking with factory keyless or SMART key if you later Unlock with the optional Pager remote, the factory alarm won't Disarm. You must use the factory remote to Unlock and Disarm factory alarm.			VELLFIRE_H20W_V2_1
	GGH3#W, AGH3#W AYH30W	2015.01 ~ 2017.12	Yes	○	○Note1	OBD	Note1: Factory Alarm & Mirror Closer not controlled by optional Pager. Hazard Flash Feature: Not possible while Ignition = ON. (IG Protect Mode triggers, etc.) ※UPS-33 recommended for non-HV cars. ※When installing Starter Kill, use optional KDR-2B Starter Kill Relay.			VELLFIRE_H30W_V2_0
	GGH3#W, AGH3#W AYH30W TSS equipped	2018.01 ~	Yes	○	△	2wire ▼	※Hood-open detection possible. ※Open BackDoor only after Unlocking. ※NT-4 PostTap Connectors required. ※1480,540 OS Firmware T39 required. (IG Protect Mode triggers, Remote Start Operation, Door Trigger while IG=ON)	Feb. 2018 GGH30W		TOYOTA_RAB2_V6_0
VOXY VOXY Hybrid	ZRR7#G, ZRR7#W	2007.06 ~ 2014.01	Yes/No	○	○	OBD	On Power BackDoor equipped cars, always Disarm the 1480 before opening BackDoor.			VOXY_R70_V2_1
	ZRR8#G, ZRR8#W ZWR80G	2014.01 ~ 2015.12 2016.01 ~	Yes	○*	○Note1	OBD 2wire▼	※Hazard Flash Feature: Not possible while Ignition = ON. (IG Protect Mode triggers, etc.) *Arms on cars with Sliding Door Reservation Locking, but may sound Error Chirp. Note1: Factory Alarm & Mirror Closer not controlled by optional Pager. (Cars without SMART not tested) ※NS-4 connectors required. ※KDR-2B required for Starter Kill. ※2016.1 ~ Speed-Lock Incompatible	2014.1 Had SMART 2014.3 Hybrid Had TSS or car maker optional navigation		VOXY_R80_V2_0 VOXY_R80_4A7_V2_0
Esquire Esquire Hybrid	ZRR8#G, ZRR8#W ZWR80G	2014.10 ~ 2015.12 2016.01 ~	Yes	○*	○Note1	OBD 2wire▼	※Hazard Flash Feature: Not possible while Ignition = ON. (IG Protect Mode triggers, etc.) *Arms on cars with Sliding Door Reservation Locking, but may sound Error Chirp. Note1: Factory Alarm & Mirror Closer not controlled by optional Pager. (Cars without SMART not tested) ※NS-4 connectors required. ※KDR-2B required for Starter Kill. ※2016.1 ~ Speed-Lock Incompatible	Had TSS		VOXY_R80_V2_0 VOXY_R80_4A7_V2_0
Estima Estima Hybrid	ACR5#, GSR5# AHR20W	2006.01 ~ 2016.05 2006.06	Yes/No	○	○	OBD	On Power BackDoor equipped cars, always Disarm the 1480 before opening BackDoor.			ESTIMA_R50_V2_1 ESTIMA_HYBRID_R20_V2_1
	ACR50W TSS equipped AHR20W TSS equipped	2016.06 ~	Yes	○	○ △	2wire ▼	※No Hazard Flashing feature. ※Optional NS-4 connectors required for CAN wire connections. ※Hazard Flash OK, except when Ignition ON. ※NS-4 required. ※1480,540 OS Firmware T39 required.	Had TSS Mar. 2017		ESTIMA_R50_V2_1 TOYOTA_RAB2_V6_0
Auris	NZE15#H, ZRE15#H	2006.10 ~ 2012.08	Yes/No	○	○	OBD	MT cars don't support Speed-Lock			AURIS_E150_V2_1
	N#E18#H, ZRE186H	2012.08 ~ 2018.03	Yes	○	○	OBD	※Hazard Flash Feature: Not possible while Ignition = ON. (IG Protect Mode triggers, etc.) ※MT cars don't support Speed-Lock	Had SMART Apr. 2015, model 120T		AURIS_E18#_V2_0
Camry	ACV4#	2006.01 ~ 2011.08	Yes/No	○	○	OBD				CAMRY_V40_V2_1
	AVV50	2011.09 ~ 2017.06	Yes	○	○	OBD	Hazard Flash Feature: Not possible while Ignition = ON. (IG Protect Mode triggers, etc.)			CAMRY_V50_V2_1
	AXVH70	2017.07 ~	Yes	○	△	2wire▼	※Hazard Flash is impossible. ※Optional NS-4 PostTap connectors required for CAN. ※Use KDR-2B for Starter Kill. ※Uses CROWN S210 vehicle firmware.	Nov. 2017		CROWN_ATHLETE S210_V2_2
Corolla AXIO	NZE14#, ZRE14#	2006.10 ~ 2012.04	Yes/No	○	○	OBD	Grade "X": Incompatible with Trunk Open. ※MT cars don't support Auto Speed-Lock			AXIO_E140_V2_1
Corolla Fielder	NZE14#G, ZRE14#G	2006.10 ~ 2012.04	Yes/No	○	○	OBD	※MT cars don't support Auto Speed-Lock			FIELDER_E140_V2_2
	NRE161G, NZE16#G ZRE162G	2012.05 ~ 2017.09	No Yes	○	○	OBD	※Hazard Flash Feature: Not possible while Ignition ON. (IG Protect Mode triggers, etc.) ※MT cars don't support Speed-Lock			FIELDER_E160_NO SMRT_V2_0 FIELDER_E160_W_SMRT_V2_0
	NKE165G Hybrid	2013.08	Yes	○	○	OBD	Hybrids with SMART use Toyota Aqua vehicle firmware. (see right)	Hybrid with SMART		AQUA_P11W_SMRT_V2_1
	NRE161G, NZE16#G ZRE162G	2017.10 ~	No Yes	○	○	2wire ▼	※Hazard Flash Feature: Not possible while Ignition ON. (IG Protect Mode triggers, etc.) ※Optional NS-4 PostTap connectors required for CAN connections. ※Never confirmed Speed-Lock operation on AT cars, and MT cars cannot use Speed-Lock at all.	Had SMART		FIELDER_E160_NO SMRT_V2_0 FIELDER_E160_W_SMRT_V2_0
Corolla Sports	NRE21#H ZWE211H (Hybrid)	2018.06 ~	Yes	○	△	2wire ▼	※Hazard Flash Feature: Not possible while Ignition ON. (IG Protect Mode triggers, etc.) ※Optional NS-4 PostTap connectors required for CAN connections. ※Cannot use Speed-Lock. ※Must use 1480,540 firmware T39 and newer.	Had SMART		TOYOTA_RAB2_V6_0
Corolla Lumion	NZE151N, ZRE15#N	2007.10 ~ 2015.12	Yes/No	○	○	OBD				RUMION_E150_V2_1
Crown Crown Hybrid	GRS20#, GWS204	2008.02 ~ 2012.11	Yes	○	○	OBD	Compatible with factory alarm			CROWN_ATHLETE_S200_V2_1
	GRS21#, AWS210, ARS210	2012.12 ~ 2016.08	Yes	○	△	OBD	※Hazard Flash Feature: Not possible while Ignition ON. (IG Protect Mode triggers, etc.)	2015 2.0L Turbo		CROWN_ATHLETE
	GRS21#, AWS210, ARS210 TSS equipped	2016.08 ~ 2018.05	Yes	○	△	2wire▼	※Aug. 2016 and later vehicles have TSS. ※Optional NS-4 connectors required for CAN connections.	Aug. 2016 Hybrid with TSS		_S210_V2_2

DIGI-LINK Smart Security COMPATIBILITY (1480/540)

★Recommended Installation Option: NS-4 or NT-4 connectors make CAN-H/L connections fast, easy & secure.

★Useful Enhancement: TR537S Two-way Paging Remote offers detailed notifications and control.

TOYOTA

IMPORTANT ○=Compatible △=No Door Lock Control

Current as of: Jan.18,2019

Car Make	Car Model	Car Year	Car has SMART Key?	Compatible with SMART Key, Factory Keyless?	OPTIONAL TR537S Paging System	CAN Connection	IMPORTANT NOTES		
							Regarding DOOR LOCKING via optional TR537S Paging System: - When Armed by Factory Remote Lock and then Disarmed by the Pager, doors will NOT Unlock. - △ symbol in the "OPTIONAL TR537S..." column means only Arm & Disarm & Notifications are available.	Notes about vehicle we tested	1480 Vehicle Firmware
Succeed	P160V *Has Factory Keyless & TSS	2016.08 ~	Factory Keyless	○	○	2wire▼	※Hazard Flash Feature: Not possible while Ignition ON. (IG Protected Mode triggers, etc.) ※Speed-Lock functions properly. ※Optional NS-4 Post-Tap connectors required for CAN connections ※Hybrid models newer than Nov. 2018 have NOT yet been compatibility-checked by us.	Sep. 2016 Factory Keyless & TSS	VITZ_P130_NO SMRT_V2_0
Sienta Sienta Hybrid	P170G	2015.07 ~ 2018.08	Yes	○ Also Arms on Reservation Lock	○Note1	OBDD	※Hazard Flash Feature: Not possible while Ignition ON. (IG Protected Mode triggers, etc.) Note1: If you Lock/Arm with factory keyless or SMART and later Disarm with the optional Pager, doors may not Unlock. If that happens, simply Arm & Disarm with the Pager. ※Sept 2018 & newer models: (1) Speed-Lock Feature unconfirmed. (2) Optional NS-4 required.	Had SMART Nov. 2018 NSP170G	SIENTA_P170_V2_1
		2018.09 ~	Yes			2wire▼	※Hazard Flash Feature: Not possible while Ignition ON. (IG Protected Mode triggers, etc.) Also Arms on Reservation Lock. ※Jul 2016 and newer, TSS-equipped cars: No Speed-Lock functionality ※Optional NS-4 Post-Tap connectors required for CAN connections	Had SMART Had SMART & TSS	SPADE_P140_V2_0
Spade	NSP140, NCP14#	2012.07 ~ 2016.06	Yes	○*	○	OBDD	※Hazard Flash Feature: Not possible while Ignition ON. (IG Protected Mode triggers, etc.) Also Arms on Reservation Lock.	Had SMART	SPADE_P140_V2_0
	P14# TSS equipped	2016.07 ~	Yes			2wire▼	※Jul 2016 and newer, TSS-equipped cars: No Speed-Lock functionality ※Optional NS-4 Post-Tap connectors required for CAN connections	Had SMART & TSS	
Noah Noah Hybrid	ZRR7#G, ZRR7#W	2007.06 ~ 2014.01	Yes/No	○	○	OBDD	On Power Back Door equipped cars, Disarm the 1480 before opening Back Door.		NOAH_R70_V2_1
	ZRR8#G, ZRR8#W	2014.01 ~ 2015.12	Yes	○ Also Arms on Reservation Lock	○Note1	OBDD	※Hazard Flash Feature: Not possible while Ignition ON. (IG Protected Mode triggers, etc.) Note1: Factory Alarm & Mirror Closer not controlled by optional Pager. (Cars without SMART untested) ※NS-4 connectors required for CAN connections ※Jan 2016 & newer cars: No Speed-Lock ※Jan 2016 & newer cars: Use KDR-2B for Starter Kill.	Jan. 2014 with SMART Mar. 2014 Hybrid Had TSS or car maker optional navigation	NOAH_R80_V2_0 NOAH_R80_3C7_V2_0
	ZWR80G	2016.01 ~	Yes			2wire▼	※Hazard Flash via CAN is impossible. Using the optional KCM-1 will flash Hazards when Siren chirps. Car must have SMART keyless and be PUSH START!!! ※This car has unstable power. We recommend installing a UPS-33 to provide stable power to the 1480. ※Hood-open Detection OK ※No Hazard Flash functionality unless you install the optional KCM-1. △Door Lock Control by optional remote impossible. ※NT-4 required for CAN connections ※This car has unstable power, so we recommend the UPS-33. ※1480/540 Firmware T39 required!! ※Hood-open detection possible. ※Hazard Flash works, except when Ignition is ON. ※Operation of Speed-Lock has not been confirmed. ※NT-4 required for CAN connections ※UPS-33 strongly recommended on this car. ※1480/540 firmware T39 required.	Had SMART & Push Start Ignition	HIACE_H200_4_V2_0
Hi-ACE	H20#V, H21#K H22#B, H22#W	2013.11 ~ 2017.11	Yes	○ Must have SMART!	△	OBDD	※Hazard Flash via CAN is impossible. Using the optional KCM-1 will flash Hazards when Siren chirps. Car must have SMART keyless and be PUSH START!!! ※This car has unstable power. We recommend installing a UPS-33 to provide stable power to the 1480. ※Hood-open Detection OK ※No Hazard Flash functionality unless you install the optional KCM-1. △Door Lock Control by optional remote impossible. ※NT-4 required for CAN connections ※This car has unstable power, so we recommend the UPS-33. ※1480/540 Firmware T39 required!! ※Hood-open detection possible. ※Hazard Flash works, except when Ignition is ON. ※Operation of Speed-Lock has not been confirmed. ※NT-4 required for CAN connections ※UPS-33 strongly recommended on this car. ※1480/540 firmware T39 required.	Had SMART & Push Start Ignition	HIACE_H200_4_V2_0
		2017.12 ~	No	○ T39 firmware only VSC&TRC required	△	2wire▼		Had SMART Jan. 2018 Had Keyless & TSS	TOYOTA_RAB2_V6_0
Hi-Lux	GUN125	2017.08 ~	Yes	○	△	2wire▼	※Hazard Flash Feature: Not possible while Ignition ON. (IG Protected Mode triggers, etc.) ※NT-4 connectors required for CAN connections ※1480/540 firmware T39 required.	Had SMART	TOYOTA_RAB2_V6_0
Harrier Harrier Hybrid	ZSU60W AVU65W	2013.12 ~ 2017.05	Yes	○	△	OBDD	※Hazard Flash Feature: Not possible while Ignition ON. (IG Protected Mode triggers, etc.) ※Hood-open Detection possible. △Optional Pager cannot control door locking. ※Optional Starter Kill requires purchase of the KDR-2B.	Had Factory Alarm	HARRIER_U6#_V2_0
	U6#W TSS equipped	2017.06 ~	Yes			2wire▼	※Vehicle has TSS. ※Optional NT-4 Post-Tap connectors required for CAN connections	Jul. 2017, 2.0L	
Blade	AZE15#H, GRE156H	2006.12 ~ 2012.04	Yes/No	○	○	OBDD			BLADE_E150_V2_1
	NZT260, ZRT26#	2007.06 ~ 2014.09	Yes/No	○	○	OBDD	※Operation of Speed-Lock has not been confirmed.		ALLION_T260_V2_1
	NZT260	2014.10 ~ 2016.05	Yes	○*	○	2wire▼	※Trunk-open detection not possible. ※Speed-Lock does not work. ※Vehicle firmware is Auris 180. ※Car models with TSS-C require NT-4 connectors for the CAN connections	1500cc i-stop Had TSS	AURIS_E18#_V2_0
Premio	NZT260 TSS equipped	2016.06 ~	Yes			2wire▼			
Prius Prius PHV	ZVW30	2009.05 ~ 2015.11	Yes	○*	○Note1	OBDD	※Cars with Solar Ventilation System & Remote AC must set the 1480's Feature No.3 to RSCM. ※Cars with a factory alarm and Remote AC have Hood-open detection and triggering (asa door). Note1: Factory Alarms unconfirmed and Nov. 2011 and newer L-Grade cars are unconfirmed.	No Factory Alarm or Remote A/C Had Factory Alarm & Remote A/C	PRIUS_ZVW30_V2_2 PRIUS_ZVW30_V2_4
	ZVW35	2012.01 ~ 2017.01	Yes			2wire▼	※Hood-open detection and triggering is possible (asa door). ※NT-4 required for CAN connections ※Hazard Flash Feature: Not possible while Ignition ON. (IG Protected Mode triggers, etc.) ※Speed-Lock impossible. ※Cars with Remote AC must program the 1480's Feature No.3 to RSCM. ※Optional Starter Kill requires purchase of the KDR-2B.		Prius_W50_V2_1
	ZVW5#	2015.12 ~	Yes	○	△	2wire▼			
	ZVW52	2017.02 ~	Yes	○*					
Prius α	ZVW4#	2011.05 ~ 2016.04	Yes	○	○	OBDD	Hazard Flash Feature: Not possible while Ignition ON. (IG Protected Mode triggers, etc.)	No Radar Cruise	PRIUS_ALPHA_ZVW40_V2_0
	ZVW4# No Radar Cruise	2016.05 ~ 2017.11	Yes			2wire▼	※May 2016 and newer models with Radar Cruise & TSS require NT-4 connectors for CAN connections ※Speed-Lock impossible.	Had Radar Cruise	
	ZVW4# Has Radar Cruise		Yes			2wire▼		Had TSS-P	
	ZVW4# TSS equipped	2017.12 ~	Yes			2wire▼			
ProBox	P160V *Has Factory Keyless & TSS	2016.08 ~	Factory Keyless	○	○	2wire▼	※Hazard Flash Feature: Not possible while Ignition ON. (IG Protected Mode triggers, etc.) ※Speed-Lock works ※Optional NT-4 Post-Tap connectors required for CAN connections ※Vehicle has TSS. ※Hybrid models newer than Nov. 2018 have NOT been compatibility-checked by us.	Sep. 2016 Had Keyless & TSS	VITZ_P130_NO SMRT_V2_0

DIGI-LINK Smart Security COMPATIBILITY (1480/540)

★Recommended Installation Option: NS-4 or NT-4 connectors make CAN-H/L connections fast, easy & secure.

★Useful Enhancement: TR537S Two-way Paging Remote offers detailed notifications and control.

TOYOTA

IMPORTANT ○=Compatible △=No Door Lock Control

Current as of: Jan.18,2019

Car Make	Car Model	Car Year	Car has SMART Key?	Compatible with SMART Key, Factory Keyless?	OPTIONAL TR537S Paging System	CAN Connection	IMPORTANT NOTES		
							Regarding DOOR LOCKING via optional TR537S Paging System: - When Armed by Factory Remote Lock and then Disarmed by the Pager, doors will NOT Unlock. - △ symbol in the "OPTIONAL TR537S." column means only Arm & Disarm & Notifications are available.	Notes about vehicle we tested	1480 Vehicle Firmware
Belta	KSP92, SCP92, NCP96	2005.11 ~ 2012.06	Yes/No	○	○	OBD	※Grade-X models do not have Trunk-open detection.		BELTA_P92_P96_V2.1
Porte	NSP140, NCP14#	2012.07 ~ 2016.06	Yes	○*	○	OBD	※Hazard Flash Feature: Not possible while Ignition ON. (IG Protected Mode triggers, etc) *1480 will Arm with Reservation Lock.	Had SMART	PORTE_P140_V2_0
	P14# TSS equipped	2016.07 ~					※July 2016 and newer models with TSS-C disable the 1480's Speed-Lock feature. ※Optional NT-4 PosiTap connectors required for CAN connections.	Had SMART & TSS	
Mark X	GRX13#	2009.10 ~ 2016.10	Yes	○	○*	OBD	*It is possible to remotely open the truck with the optional Pager.	Dec. 2016, 250S Had TSS	MARX_X_X130_V2_3
	GRX13# TSS equipped	2016.11 ~					※Vehicle has TSS-C. ※Optional NT-4 PosiTap connectors required for CAN connections. *It is possible to remotely open the truck with the optional Pager.		
Mark X Zio	ANA1#, GGA10	2007.09 ~ 2013.11	Yes/No	○	○	OBD			MARKXZIO_A10_V2_1
Ractis	SCP100, NCP10#	2005.10 ~ 2010.11	Yes/No	○	○	OBD			RACTIS_P100_V2_1
	NSP12#, NCP12#	2010.11 ~ 2016.08	No Yes	○ ○	○ ○	OBD	※Hazard Flash Feature: Not possible while Ignition ON. (IG Protected Mode triggers, etc)	Had SMART	RACTIS_P120_NO_SMRT_V2_0 RACTIS_P120_W_SMRT_V2_0
Land Cruiser	UZJ200W, URJ202W	2007.09 ~ 2015.07	Yes	○	○*	OBD	※UPS-33 recommended. *Factory alarm compatible.		LANDCRUISER_J200_V2.1
		2015.08 ~	Yes	○*	△ Hazard Flash impossible	2Wire▼	※Hood-open detection possible. *1480 will Arm with Reservation Lock. ※Hazard Flash Feature: Not possible while Ignition ON. (IG Protected Mode triggers, etc) ※NT-4 connectors required for CAN connections. ※UPS-33 recommended. ※Hazard Flash may not work with an optional remote. ※KDR-2B required for Starter Kill.	Apr. 2016, ZX	LANDCRUISER_J200_TSS_V2_0
Land Cruiser Prado	J15#W, GDJ150W	2009.09 ~ 2017.08	Yes	○	○*	OBD	※Backdoor glass hatch-open detection OK. ※Speed-Lock unconfirmed. *Factory alarm compatible.	Aug. 2015, Diesel	LANDCRUISER_J150_V2.1
	J15#W TSS equipped	2017.09 ~	Yes	○NOTE1	△	2Wire▼	※Hazard Flash Feature: Not possible while Ignition ON. (IG Protected Mode triggers, etc) Note1: Backdoor glass hatch-open detection is not possible, so Disarm before opening hatch. ※NT-4 connectors required for CAN connections. ※UPS-33 recommended.	Sep. 2017, Had TSS GDJ151W	HARRIER_U6#_V2_0
Legius ACE	H20#V, H21#K	2013.11 ~ 2017.11	Yes	○ Must have SMART!	△	OBD	Hazard Flash not possible by CAN, but the optional KCM-1 can flash Hazards during siren blast. Only compatible on vehicles with SMART and PUSH START!	Had SMART & Push Start Ignition	HIACE_H200_4_V2_0
		2017.12 ~	Yes	○ T39 Firmware only	△	2Wire▼	※UPS-33 recommended because 12V power on this vehicle is unstable. ※Hood-open detection possible. ※Hazard Flash impossible, except when using the optional KCM-1. △Door Lock Control impossible with optional remote. ※NT-4 required for CAN connections	Feb. 2018 Had SMART	TOYOTA_RAB2_V6_0
			No	○ VSC&TRC	△		※UPS-33 recommended. ※Must use 1480/540 firmware T39. ※Hood-open detection possible. ※Hazard Flash works except while Ignition is ON. ※Speed-Lock unconfirmed. ※Optional NT-4 connectors required for CAN connections. ※UPS-33 recommended because 12V power on this vehicle is unstable.	Jan. 2018 Had Keyless & TSS	

NOTE: Although a vehicle may be compatible above, minor vehicle changes by car maker or dealer can result in partial or complete malfunction of the 1480.

▼ Always use NS-4 or NT-4 (Posi-Tap 4-pack) connectors when connecting directly to CAN wires.

NOTE: We cannot guarantee proper 1480 operation if 3rd party CAN devices are connected at the same time. The 1480 will not cause malfunction, but other products may cause 1480 malfunction.

NOTE: Some 1480 functions may be disabled depending on various car settings.

NOTE: Vehicles with Power Sliding Door RESERVATION LOCK function: 1480 will Arm but an audible Error Chirp may be heard.

NOTE: The △ symbol in the chart above means Door Lock Control by the optional TR537S Paging System is not possible. On these cars, only Arm & Disarm & Pager Notifications are possible using the Pager remote.

OS Firmware T39: User-programmable Relay Attack Countermeasure "Feature No.2" is available only when you burn "TOYOTA_RAB2_V6_0" to the 1480 (except Toyota 86 & HI-ACE Type-4).

Speed-Lock will not work when using "TOYOTA_RAB2_V6_0" firmware, and Door Lock Control may be impossible on some cars when you add an optional VISION remote.

For vehicles experiencing large voltage drops, we strongly recommend purchase of the optional UPS-33.